

PCS OPTIONAL EXTRAS

Metal storage and transport box

B



Dimensions in mm				
Model	Length	Width	Height	For set
FSB1	640	360	150	PCS50 to PCS502
MSB1	890	300	210	PCS506 to PCS603H

Gauge and gauge block kit



Model	Description
HG1K	100mm dry gauge 0-700 Bar / 0-10000 PSI and gauge mounting block
HG63K	63mm glycerine filled gauge 0-700 Bar / 0-10000 PSI and gauge mounting block



Substitute the manual hydraulic pump for an electric driven or air driven pump.
Contact your local dealer or regional office for more information.

